

Facility Name: Utica Resource Operating, LLC – Commissioners Well Pad

Facility Location: 39.9996, -81.4398, Wills Township, Ohio

Date of Inspection: April 18, 2019

APPENDIX A: DIGITAL IMAGE/VIDEO LOG

1. Inspector Name: Victoria Nelson	2. Dates of Inspection: April 18, 2019
3. Company/Facility Name: Utica Resource Operating, LLC – Commissioners Well Pad	4. Street Address, City, State: 39.9996, -81.4398, Wills Township, Ohio
5. Number of Images and Videos: 11	6. Archival Record Location: C:\Users\Vnelson\OneDrive - Environmental Protection Agency (EPA)\MyCases\Utica Resource\Inspection Reports

Video Number	File Name	Date	Description of Video
1	MOV_2352.mp4	4/18/2019	Emissions from combustor stack
2	MOV_2353.mp4	4/18/2019	Hydrocarbon emissions from thief hatches – view from ground level
3	MOV_2354.mp4	4/18/2019	Emissions from Tank 75671 thief hatch
4	MOV_2355.mp4	4/18/2019	Emissions from Tank 75161 thief hatch
5	MOV_2356.mp4	4/18/2019	Wide angle view of top of tank battery
6	MOV_2357.mp4	4/18/2019	Emissions from Tank 75672 thief hatch
7	MOV_2358.mp4	4/18/2019	Emissions from Tank 75160 thief hatch
8	MOV_2359.mp4	4/18/2019	Emissions from Tank 75675 thief hatch
9	MOV_2360.mp4	4/18/2019	Emissions from Tank 75676 level meter

Image Number	File Name	Date and Time (Eastern Time)	Latitude and Longitude	Description of Image
1	P4180023.JPG	4/18/2019 11:09:15 AM	39.989167, -81.386111	Staining and paraffin build-up at Tank 75673 thief hatch
2	P4180024.JPG	4/18/2019 11:10:23 AM	39.998955, -81.437618	Staining and condensate droplets at Tank 75674 thief hatch